

THE
**FIRE
HOUSE** Group

FireGuard Limited

01709 579991

South Anston Fire Extinguishers

01709 584023

West Yorkshire Fire & Security

01134 264606

www.thefirehousegroup.co.uk
admin@thefirehousegroup.co.uk

Trent Valley Kart Club

FIRE EXTINGUISHER VISIT REPORT



Please Note: Only the Fireguard Limited company has the BAFE certification. If you are not under the Fireguard Company and require the BAFE certification, please advise us and we will swap the company that handles your account. This will not occur any additional fees.

British Standards recommends the Fire Extinguishers are
Services on an Annual Basis



- Fireguard
 S.A.F.E.
 W.Y.F.S.

The Fire House
 Unit 2 Swinton Bridge Workshops,
 Rowms Lane, Swinton,
 Rotherham, S64 8AE

FIRE EXTINGUISHER VISIT REPORT

COMPANY NAME	Trent Valley Kart Club
SITE ADDRESS	P.F International Kart Circuit Brandon Grantham NG32 2AY

TECHNICIAN	Paul Thorpe
DATE	18/5/2021 11:20 am
LOG BOOK COMPLETED	Yes: No: <input checked="" type="checkbox"/>
NEW CUSTOMER	
QUOTED WORK (REF)	
PO NUMBER	

WORK CARRIED OUT										
EQUIPMENT	SIZE	EXTINGUISHERS SERVICED	PASSED	FAILED	EXTINGUISHERS INSTALLED	R/N	PRICE OF EXTINGUISHER	TOTAL COST OF NEW EXTINGUISHERS	ID SIGN INSTALLED	DISPOSAL
WATER	3LTR	2	2	0						
	6LTR									
	9LTR									
WATER WITH ADDITIVE	3LTR									
	6LTR									
	9LR									
CO2	2KG	2	2	0						
	5KG									
FOAM	1LTR									
	2LTR									
	3LTR	1	1	0						
	6LTR	13	13	0						
WET CHEMICAL	9LTR									
	2LTR									
	3LTR									
	6LTR									
POWDER	1KG									
	2KG	10	10	0						
	4KG									
	6KG	3	3	0						
	9KG									
MULTI CHEM	2LTR									
	3LTR									
	4LTR									
	6LTR									
F. BLANKET										
HOSE REEL										
D CLASS										
TOTALS		31	31	0	0		£0.00	0	0	

OTHER SERVICES AVAILABLE	
ITEM	TICK
Fire Risk Assessments	
Fire Alarm Installation / Service	
Emergency Light Installation / Service	
Fire Marshall Training	
Live Extinguisher Training	
Fire Suppression Installation / Service	
Fire Sprinkler Installation / Service	
Gas Systems Installation / Service	
Pat Testing	
Periodic Fixed Wire Testing	
CCTV Installation / Service	
Door Access Installation / Service	
Nurse Call Systems	

CUSTOMER INFO	
Telephone Number:	01632 626424 (james -site contact 0791936)
	danielle@tvkc.co.uk
Contact Name:	Danielle/ Nigel/Clare
Accounts Email Address:	
Further Information:	TRENT001

EXTRA ITEMS PURCHASED			
QTY	ITEM	PPU	TOTAL
TOTAL COST			£0.00

ENGINEERS COMMENTS

COSTINGS			
SERVICING COST PER UNIT		TOTAL COST	£0.00
FIXED SERVICING COST	£115.77	TOTAL COST	£115.77
NEW FIRE EXTINGUISHERS		TOTAL COST	£0.00
ATTENDANCE FEE		TOTAL COST	
SIGNS COST PER UNIT		TOTAL COST	£0.00
DISPOSAL COST PER UNIT		TOTAL COST	£0.00
EXTRA ITEMS PURCHASED		TOTAL COST	£0.00

PAYMENT METHOD	
CASH	
CHEQUE	
ACCOUNT	

TOTAL AMOUNT PAYABLE	
TOTAL COST (EXCL. VAT)	£115.77
TOTAL COST (INC. VAT)	£138.92



- Fireguard
- S.A.F.E.
- W.Y.F.S.

The Fire House
 Unit 2 Swinton Bridge Workshops,
 Rowms Lane, Swinton,
 Rotherham, S64 8AE

**FIRE EXTINGUISHER VISIT
 REPORT**

RECOMMENDATIONS/REPLACEMENTS - IF NOT COMPLETED ON THE 1ST VISIT.

QTY	LOCATION/DESCRIPTION	ITEM	PPU	TOTAL

TOTAL COST OF RECOMMENDATIONS/REPLACEMENTS

TOTAL COST (EXCL. VAT)	£0.00
TOTAL COST (INC. VAT)	£0.00


SERVICING STANDARDS

The Firehouse Group have serviced the fire extinguishers and other fire protection equipment within the premises identified above in accordance with the requirements and frequencies indicated by BS5306 part 3 and refilled when required in accordance with BS5306 part 9.
 According to BS5306 part 3, it is the duty of the responsible person in the premises to inspect extinguishers at monthly intervals.
 P50 fire extinguishers are inspected in accordance with manufacturers recommendations.

WASTE TRANSFER INFORMATION

If any fire extinguishers are taken away from your site (identified in the disposal section), please see below the waste transfer and registration information.
 Waste Transfer Registration Number: CBDL285178. EWC Code: 16.05.05
 Some Fire Extinguishers are used for training and the remainder are broken down (the aluminium, plastic, steel & contents are all separated). Each component is collected by a 3rd party for recycling (powder is used for fertilizer). Copies of the 3rd parties waste transfer information is available upon request.

COMPLETION

CUSTOMER NAME	Danielle
CUSTOMER EMAIL ADDRESS	danielle@tvkc.co.uk
DATE	18/5/2021 12:13 pm
SIGNATURE	
CUSTOMER COMMENTS/FEEDBACK	



Fireguard

S.A.F.E.

W.Y.F.S.

The Fire House
Unit 2 Swinton Bridge Workshops,
Rowms Lane, Swinton,
Rotherham, S64 8AE

FIRE EXTINGUISHER VISIT REPORT

DATE: 18/5/2021 11:20 am

TECHNICIAN: Paul Thorpe

ASSET LIST:

FIRE EXTINGUISHER DTR DATES													
FIRE EXTINGUISHER	TOTAL	2020	2021	2022	2023	2024	2025	2026	2027	2028	2029	2030	2031
1KG POWDER													
2KG POWDER	10			7	1	2							
3KG POWDER													
4KG POWDER													
6KG POWDER	3			3									
9KG POWDER													
1LTR FOAM													
2LTR FOAM													
3LTR FOAM	1					1							
6LTR FOAM	13			10	3								
9LTR FOAM													
3LTR WATER	2					2							
6LTR WATER													
9LTR WATER													
2LTR WET CHEMICAL													
3LTR WET CHEMICAL													
6LTR WET CHEMICAL													
2KG CO2	2			1	1								
5KG CO2													
FIRE BLANKET													
TOTAL NUMBER OF EXTINGUISHERS AND FIRE BLANKETS ON SITE:												31	

FOR ENGINEERS USE ONLY	
SITE ADDRESS & LOCATION NOTES Trent Valley Kart Club P.F International Kart Circuit Brandon Grantham NG32 2AY	ENGINEERS COMMENTS



Certificate of Inspection

Fire Extinguishers

Date: 18/5/2021

Inspection carried out at:

Trent Valley Kart Club
P.F International Kart Circuit
Brandon
Grantham
NG32 2AY

Technicians Name: Paul Thorpe

We hereby certify all the Fire Extinguishers at the above premises was inspected on the above date in accordance with BS5306/European Directives.

Routine Inspection by user:- BS5306-3:2017 Part 3 section (6) Recommends the user to regularly inspects all extinguishers, replacement charges etc. to make sure that they are in the proper position and are in working order.

The inspections should be carried out annually and you are advised to retain this certificate as proof of an inspection.



Extinguisher Type	On Site	Passed	Failed
Dry Powder	13	13	0
Water	2	2	0
Co2	2	2	0
Foam	14	14	0
Wet Chemical	0	0	0
Fire Blanket	0	0	0
Hose Reel	0	0	0
Multi Chem	0	0	0
D Class	0	0	0

The Fire House Group

Unit 2 Swinton Bridge Workshops
Rowms Lane
Swinton
Rotherham
S64 8AE

Phone:
0844 693 1150

Email:
admin@thefirehousegroup.co.uk





DID YOU KNOW...

- Fire Alarm Systems should be serviced on a 6 monthly basis?
- Emergency Lighting should be serviced on an annual basis?
- Fire Risk Assessments should be conducted then reviewed on an annual basis?
- Periodic Inspections should be conducted on a 5 yearly basis?
- You should have employees that are trained fire marshals?
- Fire Extinguishers should be serviced on an annual basis?

DID YOU ALSO KNOW...

We can also offer the below:

- Fire Extinguisher Sales/Service
- Fire Alarm Installation/Service
- Emergency Lighting Installation/Service
- Fire Risk Assessments
- PAT Testing
- CCTV Installation/Maintenance
- Door Access Installation/Maintenance
- Gas Inspection Certificates
- Intruder Alarm Installation/Maintenance
- Fire Training

NEW SERVICES...

- Electrical Installations
- New Sockets
- New Lighting Installations
- Electrical Testing
- Fuse Board Upgrades/Changes
- Periodic Inspection

If you need assistance with any of these services please give us a call for a Free No Obligation Quotation on:

0844 693 1150

OR

Visit our website:

www.thefirehousegroup.co.uk