

This is to certify that

# Keith Ramsbottom

Of KMR Services

Has serviced and maintained the fire fighting equipment at Shenington Kart Race Club in strict compliance with BS 5306 Part 3,2000 on 19<sup>th</sup> March 2021

As listed below

**8 x 2Kg Co2, 8 x 6Lt AFFF, 5 X 9Kg Dry Powder  
12 x 6Kg Dry Powder, 1 x 2 Kg Dry Powder, 9 x 6Lt Water +1 x Fire blanket,  
2 x F-500 lithium battery extinguishers &  
12 x 9lt Water Extinguishers**

Inspection by the User:

It is recommended that regular visual inspection of all portable extinguishers should be carried out by the user's representative at intervals, not more then monthly (BS 5306 Part 3, 2000, Section 4) and preferably weekly, Fire Precautions (Workplace) Regulations.

Checks should include:

The extinguisher is located in the designated place,  
Is unobstructed, visible and its operating instructions face outwards,  
Has operating instructions which are clear and legible,  
Is not obviously damaged, has a reading in the operable range  
Or position of any pressure gauge or indicator fitted, has seals and tamper  
Indicators, which are not broken or missing.

If any for the above do not comply the information shall be passed to the above at the following email address. [keith.ramsbottom@virgin.net](mailto:keith.ramsbottom@virgin.net) A.S.A.P. so the fault can be rectified.

# KMR SERVICES

**Fire safety engineer**